

Riverina Beef
Regulator Road, Yanco N.S.W. 2703

ANALYSIS REPORT

Report Number: CIC12-023

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 9

The samples were analysed as received by the laboratory.

Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
26/11/12	2579	Region:Coly, Id:57, Acro:DC400D	<LOR
26/11/12	2580	Region:Coly, Id:3, Acro:DC500A	<LOR
26/11/12	2581	Region:Argoon, Id:5, Acro:CODA	<LOR
26/11/12	2582	Region:Coly, Id:13, Acro:DC500B	<LOR
26/11/12	2583	Region:Argoon, Id:17, Acro:DC800D	<LOR
26/11/12	2584	Region:Yamma, Id:18, Acro:DC800A	<LOR
26/11/12	2585	Region:Yamma, Id:58, Acro:DC800B	<LOR
26/11/12	2586	Region:Yamma, Id:19, Acro:DC800C	<LOR
26/11/12	2587	Region:Yamma, Id:20, Acro:DC830A	<LOR
26/11/12	2588	Region:Yamma, Id:25, Acro:DC840B	<LOR
26/11/12	2589	Region:Coly, Id:33, Acro:DC550A	<LOR
26/11/12	2590	Region:Boona, Id:50, Acro:DC530A	<LOR
26/11/12	2591	Region:Boona, Id:49, Acro:DC500C	<LOR
26/11/12	2592	Region:Boona, Id:56, Acro:CCS	<LOR
26/11/12	2592	Region:Boona, Id:56, Acro:CCS	<LOR