

	<p>JBS Australia RIVERINA BEEF Regulator Road Yanco NSW 2703</p> <p>Analysis Report</p>	<p>Report No: CIC14-11a</p> <p>This report replaces CIC14-11</p>
---	--	---

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 4

Date of analysis: 3rd November 2014

The samples were analysed as received by the laboratory.

Results for Molinate screen

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
2/11/2014	E0912	Region:Argoon, Id:5, Acro:CODW	<LOR
2/11/2014	E0919	Region:Coly, Id:57, Acro:DC400D	<LOR
2/11/2014	E0920	Region:Coly, Id:3, Acro:DC500A	<LOR
2/11/2014	E0921	Region:Coly, Id:13, Acro:DC500B	<LOR
2/11/2014	E0922	Region:Argoon, Id:16, Acro:DC820A	<LOR
2/11/2014	E0923	Region:Argoon, Id:17, Acro:DC800D	<LOR
2/11/2014	E0924	Region:Yamma, Id:18, Acro:DC800A	<LOR
2/11/2014	E0925	Region:Yamma, Id:58, Acro:DC800B	<LOR
2/11/2014	E0926	Region:Yamma, Id:19, Acro:DC800C	Molinate 0.93ug/L
2/11/2014	E0927	Region:Yamma, Id:20, Acro:DC830A	<LOR
2/11/2014	E0928	Region:Yamma, Id:25, Acro:DC840B	<LOR
2/11/2014	E0929	Region:Coly, Id:33, Acro:DC550A	<LOR
2/11/2014	E0930	Region:Boona, Id:56, Acro:CCS	<LOR
2/11/2014	E0931	Region:Boona, Id:1, Acro:DC400C	<LOR