

**Riverina Beef**  
Regulator Road, Yanco N.S.W. 2703

**ANALYSIS REPORT**

**Report Number:** CIC12-021

**Customer:** Coleambally Irrigation Co-operative

**Sample Description:** Irrigation Water – Week 8

The samples were analysed as received by the laboratory.

**Results for Molinate screen:**

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
19/11/2012	2524	Region:Coly, Id:54, Acro:CE160-2	<LOR
19/11/2012	2525	Region:Coly, Id:57, Acro:DC400D	<LOR
19/11/2012	2526	Region:Coly, Id:3, Acro:DC500A	<LOR
19/11/2012	2527	Region:Argoon, Id:5, Acro:CODA	<LOR
19/11/2012	2528	Region:Argoon, Id:6, Acro:DC600A	<LOR
19/11/2012	2529	Region:Coly, Id:13, Acro:DC500B	Molinate 0.56
19/11/2012	2530	Region:Coly, Id:33, Acro:DC550A	Molinate 6.2
19/11/2012	2531	Region:Boona, Id:50, Acro:DC530A	<LOR
19/11/2012	2532	Region:Boona, Id:49, Acro:DC500C	<LOR
19/11/2012	2533	Region:Boona, Id:46, Acro:DC400B	<LOR
19/11/2012	2534	Region:Boona, Id:56, Acro:CCS	<LOR
19/11/2012	2535	Region:Argoon, Id:16, Acro:DC820A	<LOR
19/11/2012	2536	Region:Argoon, Id:17, Acro:DC800D	Molinate 15
19/11/2012	2537	Region:Yamma, Id:18, Acro:DC800A	Molinate 16
19/11/2012	2538	Region:Yamma, Id:58, Acro:DC800B	<LOR
19/11/2012	2539	Region:Yamma, Id:19, Acro:DC800C	<LOR
19/11/2012	2540	Region:Yamma, Id:20, Acro:DC830A	<LOR
19/11/2012	2541	Region:Yamma, Id:25, Acro:DC840B	<LOR