

Riverina Beef

Regulator Road, Yanco N.S.W. 2703

ANALYSIS REPORT

Report Number: CIC13-20

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 12

The samples were analysed as received by the laboratory.

Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate ($\mu\text{g/L}$)
16/12/13	2336	Region:Coly, Id:3, Acro:DC500A	<LOR
16/12/13	2337	Region:Argoon, Id:5, Acro:CODA	<LOR
16/12/13	2338	Region:Coly, Id:13, Acro:DC500B	<LOR
16/12/13	2339	Region:Argoon, Id:14, Acro:DC600B	<LOR
16/12/13	2340	Region:Argoon, Id:17, Acro:DC800D	<LOR
16/12/13	2341	Region:Yamma, Id:18, Acro:DC800A	<LOR
16/12/13	2342	Region:Yamma, Id:58, Acro:DC800B	<LOR
16/12/13	2343	Region:Yamma, Id:19, Acro:DC800C	<LOR
16/12/13	2344	Region:Yamma, Id:20, Acro:DC830A	<LOR
16/12/13	2345	Region:Yamma, Id:39, Acro:CCD	<LOR
16/12/13	2346	Region:Boona, Id:49, Acro:DC500C	Molinate 1.3ug/L
16/12/13	2347	Region:Boona, Id:56, Acro:CCS	<LOR