

ANALYSIS REPORT

Report Number: CIC12-011

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 3

The samples were analysed as received by the laboratory.

Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
15/10/2012	2219	Region:Coly, Id:54, Acro:CE160-2	<LOR
15/10/2012	2220	Region:Coly, Id:57, Acro:DC400D	Molinate 1.3
15/10/2012	2221	Region:Coly, Id:3, Acro:DC500A	Molinate 2.4
15/10/2012	2222	Region:Argoon, Id:5, Acro:CODA	Molinate 2.1
15/10/2012	2223	Region:Argoon, Id:6, Acro:DC600A	<LOR
15/10/2012	2224	Region:Coly, Id:13, Acro:DC500B	Molinate 2.5
15/10/2012	2225	Region:Argoon, Id:14, Acro:DC600B	Molinate 17
15/10/2012	2226	Region:Argoon, Id:16, Acro:DC820A	<LOR
15/10/2012	2227	Region:Argoon, Id:17, Acro:DC800D	<LOR
15/10/2012	2228	Region:Yamma, Id:18, Acro:DC800A	<LOR
15/10/2012	2229	Region:Yamma, Id:58, Acro:DC800B	<LOR
15/10/2012	2230	Region:Yamma, Id:19, Acro:DC800C	<LOR
15/10/2012	2231	Region:Yamma, Id:20, Acro:DC830A	<LOR
15/10/2012	2232	Region:Yamma, Id:25, Acro:DC840B	<LOR
15/10/2012	2233	Region:Yamma, Id:39, Acro:CCD	<LOR
15/10/2012	2234	Region:Boona, Id:50, Acro:DC530A	<LOR

Riverina Beef

Regulator Road, Yanco N.S.W. 2703

ANALYSIS REPORT

Date of sample	Sample Number	Sample Description (Type)	Molinate ($\mu\text{g/L}$)
15/10/2012	2235	Region:Boona, Id:49, Acro:DC500C	<LOR
15/10/2012	2236	Region:Boona, Id:56, Acro:CCS	<LOR