

	<p align="center">JBS Australia RIVERINA BEEF Regulator Road Yanco NSW 2703</p>	<p>Report No: CIC14-09a This report replaces CIC14-09</p>
<p align="center">Analysis Report</p>		

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 3

Date of analysis: 27th October, 2014

The samples were analysed as received by the laboratory.

Results for Molinate screen

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
27/10/2014	E0864	Region:Argoon, Id:5, Acro:CODW	<LOR
27/10/2014	E0865	Region:Coly, Id:13, Acro:DC500B	<LOR
27/10/2014	E0869	Region:Coly, Id:3, Acro:DC500A	<LOR
27/10/2014	E0870	Region:Coly, Id:57, Acro:DC400D	<LOR
27/10/2014	E0871	Region:Argoon, Id:16, Acro:DC820A	<LOR
27/10/2014	E0873	Region:Argoon, Id:17, Acro:DC800D	<LOR
27/10/2014	E0874	Region:Yamma, Id:18, Acro:DC800A	<LOR
27/10/2014	E0875	Region:Yamma, Id:58, Acro:DC800B	<LOR
27/10/2014	E0876	Region:Yamma, Id:19, Acro:DC800C	<LOR
27/10/2014	E0877	Region:Yamma, Id:20, Acro:DC830A	<LOR
27/10/2014	E0878	Region:Yamma, Id:25, Acro:DC840B	<LOR
27/10/2014	E0879	Region:Coly, Id:33, Acro:DC550A	<LOR
27/10/2014	E0880	Region:Boona, Id:49, Acro:DC500C	<LOR
27/10/2014	E0881	Region:Boona, Id:56, Acro:CCS	<LOR