

Riverina Beef

Regulator Road, Yanco N.S.W. 2703

ANALYSIS REPORT

Report Number: CIC13-19

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 11

The samples were analysed as received by the laboratory.

Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate ($\mu\text{g/L}$)
9/12/13	2285	Region:Coly, Id:3, Acro:DC500A	<LOR
9/12/13	2286	Region:Coly, Id:13, Acro:DC500B	<LOR
9/12/13	2287	Region:Argoon, Id:16, Acro:DC820A	<LOR
9/12/13	2288	Region:Argoon, Id:17, Acro:DC800D	<LOR
9/12/13	2289	Region:Yamma, Id:18, Acro:DC800A	<LOR.
9/12/13	2290	Region:Yamma, Id:58, Acro:DC800B	<LOR
9/12/13	2291	Region:Yamma, Id:19, Acro:DC800C	<LOR
9/12/13	2292	Region:Yamma, Id:20, Acro:DC830A	<LOR
9/12/13	2293	Region:Yamma, Id:25, Acro:DC840B	<LOR
9/12/13	2294	Region:Yamma, Id:39, Acro:CCD	<LOR
9/12/13	2295	Region:Boona, Id:50, Acro:DC530A	<LOR
9/12/13	2296	Region:Boona, Id:46, Acro:DC400B	<LOR