

Riverina Beef
Regulator Road, Yanco N.S.W. 2703

ANALYSIS REPORT

Report Number: CIC12-017

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 6

The samples were analysed as received by the laboratory.

Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
5/11/2012	2407	Region:Coly, Id:54, Acro:CE160-2	<LOR
5/11/2012	2408	Region:Coly, Id:57, Acro:DC400D	<LOR
5/11/2012	2409	Region:Coly, Id:3, Acro:DC500A	<LOR
5/11/2012	2410	Region:Argoon, Id:5, Acro:CODA	Molinate 0.73
5/11/2012	2411	Region:Argoon, Id:6, Acro:DC600A	<LOR
5/11/2012	2412	Region:Coly, Id:13, Acro:DC500B	Molinate 2.2
5/11/2012	2413	Region:Argoon, Id:16, Acro:DC820A	Molinate 2.2
5/11/2012	2414	Region:Argoon, Id:17, Acro:DC800D	<LOR
5/11/2012	2415	Region:Yamma, Id:18, Acro:DC800A	<LOR
5/11/2012	2416	Region:Yamma, Id:58, Acro:DC800B	<LOR
5/11/2012	2417	Region:Yamma, Id:19, Acro:DC800C	Molinate 0.75
5/11/2012	2418	Region:Yamma, Id:20, Acro:DC830A	<LOR
5/11/2012	2419	Region:Yamma, Id:25, Acro:DC840B	<LOR
5/11/2012	2420	Region:Yamma, Id:39, Acro:CCD	<LOR
5/11/2012	2421	Region:Coly, Id:33, Acro:DC550A	<LOR
5/11/2012	2422	Region:Boona, Id:50, Acro:DC530A	<LOR
5/11/2012	2423	Region:Boona, Id:49, Acro:DC500C	Molinate 1.5

Riverina Beef
Regulator Road, Yanco N.S.W. 2703

ANALYSIS REPORT

Date of sample	Sample Number	Sample Description (Type)	Mollinate ($\mu\text{g/L}$)
5/11/2012	2424	Region:Boona, Id:56, Acro:CCS	<LOR