

**ANALYSIS REPORT**

**Report Number:** CIC12-007

**Customer:** Coleambally Irrigation Co-operative

**Sample Description:** Irrigation Water – Week 1

The samples were analysed as received by the laboratory.

**Results for Molinate screen:**

<b>Date of sample</b>	<b>Sample Number</b>	<b>Sample Description (Type)</b>	<b>Molinate (µg/L)</b>
2/10/2012	2053	Region:Coly, Id:3, Acro:DC500A	<LOR
2/10/2012	2054	Region:Argoon, Id:5, Acro:CODA	<LOR
2/10/2012	2055	Region:Argoon, Id:6, Acro:DC600A	<LOR
2/10/2012	2056	Region:Coly, Id:13, Acro:DC500B	<LOR
2/10/2012	2057	Region:Argoon, Id:14, Acro:DC600B	<LOR
2/10/2012	2058	Region:Argoon, Id:17, Acro:DC800D	<LOR
2/10/2012	2059	Region:Yamma, Id:18, Acro:DC800A	<LOR
2/10/2012	2060	Region:Yamma, Id:58, Acro:DC800B	<LOR
2/10/2012	2061	Region:Yamma, Id:19, Acro:DC800C	<LOR
2/10/2012	2062	Region:Yamma, Id:20, Acro:DC830A	<LOR
2/10/2012	2063	Region:Yamma, Id:25, Acro:DC840B	<LOR
2/10/2012	2064	Region:Yamma, Id:39, Acro:CCD	<LOR
2/10/2012	2065	Region:Boona, Id:50, Acro:DC530A	<LOR
2/10/2012	2068	Region:Boona, Id:49, Acro:DC500C	<LOR
2/10/2012	2069	Region:Boona, Id:56, Acro:CCS	<LOR