

## ANALYSIS REPORT

**Report Number:** CIC13-10

**Customer:** Coleambally Irrigation Co-operative

**Sample Description:** Irrigation Water – Week 3

The samples were analysed as received by the laboratory.

**Results for Molinate screen:**

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
14/10/13	1837	Region:Coly, Id:57, Acro:DC400D	<LOR
14/10/13	1838	Region:Coly, Id:3, Acro:DC500A	<LOR
14/10/13	1839	Region:Argoon, Id:5, Acro:CODA	<LOR
14/10/13	1840	Region:Argoon, Id:6, Acro:DC600A	<LOR
14/10/13	1841	Region:Coly, Id:13, Acro:DC500B	<LOR
14/10/13	1842	Region:Argoon, Id:16, Acro:DC820A	<LOR
14/10/13	1843	Region:Argoon, Id:17, Acro:DC800D	<LOR
14/10/13	1844	Region:Yamma, Id:18, Acro:DC800A	<LOR
14/10/13	1845	Region:Yamma, Id:58, Acro:DC800B	<LOR
14/10/13	1846	Region:Yamma, Id:19, Acro:DC800C	<LOR
14/10/13	1847	Region:Yamma, Id:20, Acro:DC830A	<LOR
14/10/13	1848	Region:Yamma, Id:25, Acro:DC840B	<LOR
14/10/13	1849	Region:Yamma, Id:39, Acro:CCD	<LOR
14/10/13	1850	Region:Coly, Id:33, Acro:DC550A	<LOR
14/10/13	1851	Region:Boona, Id:56, Acro:CCS	<LOR
10/10/13	1852	DC600 Id:70	<LOR