

	JBS Australia RIVERINA BEEF Regulator Road Yanco NSW 2703 Analysis Report	Report No: CIC14-18
---	---	--------------------------------------

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 7

Date of analysis: 24th November 2014

The samples were analysed as received by the laboratory.

Results for Molinate screen

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
24/11/2014	E1073	Region:Coly, Id:3, Acro:DC500A	<LOR
24/11/2014	E1074	Region:Argoon, Id:5, Acro:CODW	<LOR
24/11/2014	E1075	Region:Argoon, Id:17, Acro:DC800D	<LOR
24/11/2014	E1076	Region:Yamma, Id:18, Acro:DC800A	<LOR
24/11/2014	E1077	Region:Yamma, Id:58, Acro:DC800B	<LOR
24/11/2014	E1078	Region:Yamma, Id:19, Acro:DC800C	<LOR
24/11/2014	E1079	Region:Yamma, Id:20, Acro:DC830A	<LOR
24/11/2014	E1080	Region:Yamma, Id:25, Acro:DC840B	<LOR
24/11/2014	E1081	Region:Boona, Id:49, Acro:DC500C	<LOR
24/11/2014	E1082	Region:Boona, Id:56, Acro:CCS	<LOR