



JBS Australia
RIVERINA BEEF
Regulator Road Yanco NSW 2703

Analysis Report

Report No:

CIC14-08b

This report replaces
CIC14-08a

Report Number: CIC14-08b
Customer: Coleambally Irrigation Co-operative
Sample Description: Irrigation Water – Week 2
Date of analysis: 20th October, 2014

The samples were analysed as received by the laboratory.

Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate ($\mu\text{g/L}$)
20/10/2014	E0825	Region:Coly, Id:3, Acro:DC500A	<LOR
20/10/2014	E0826	Region:Argoon, Id:5, Acro:CODA	<LOR
20/10/2014	E0827	Region:Coly, Id:13, Acro:DC500B	<LOR
20/10/2014	E0830	Region:Coly, Id:57, Acro:DC400D	<LOR
20/10/2014	E0831	Region:Argoon, Id:6, Acro:DC600A	<LOR
20/10/2014	E0832	Region:Coly, Id:33, Acro:DC550A	<LOR
20/10/2014	E0833	Region:Argoon, Id:17, Acro:DC800D	<LOR
20/10/2014	E0834	Region:Yamma, Id:18, Acro:DC800A	<LOR
20/10/2014	E0835	Region:Yamma, Id:58, Acro:DC800B	<LOR
20/10/2014	E0836	Region:Yamma, Id:19, Acro:DC800C	<LOR
20/10/2014	E0837	Region:Yamma, Id:20, Acro:DC830A	<LOR
20/10/2014	E0838	Region:Yamma, Id:25, Acro:DC840B	<LOR
20/10/2014	E0839	Region:Boona, Id:49, Acro:DC500C	<LOR
20/10/2014	E0840	Region:Boona, Id:56, Acro:CCS	<LOR