

	<p>JBS Australia RIVERINA BEEF Regulator Road Yanco NSW 2703</p> <p>Analysis Report</p>	<p>Report No: CIC14-16</p>
---	--	--

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 6

Date of analysis: 17th November 2014

The samples were analysed as received by the laboratory.

Results for Molinate screen

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
17/11/2014	E1008	Region:Coly, Id:3, Acro:DC500A	<LOR
14/11/2014	E1009	Region:Argoon, Id:5, Acro:CODW	<LOR
14/11/2014	E1010	Region:Coly, Id:13, Acro:DC500B	<LOR
14/11/2014	E1011	Region:Argoon, Id:16, Acro:DC820A	Molinate 41ug/L
17/11/2014	E1012	Region:Argoon, Id:17, Acro:DC800D	Molinate 25ug/L
17/11/2014	E1013	Region:Yamma, Id:18, Acro:DC800A	<LOR
17/11/2014	E1014	Region:Yamma, Id:58, Acro:DC800B	<LOR
17/11/2014	E1015	Region:Yamma, Id:19, Acro:DC800C	<LOR
17/11/2014	E1016	Region:Yamma, Id:20, Acro:DC830A	<LOR
17/11/2014	E1017	Region:Yamma, Id:25, Acro:DC840B	<LOR
14/11/2014	E1018	Region:Boona, Id:56, Acro:CCS	<LOR