

ANALYSIS REPORT

Report Number: CIC13-06

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 1

The samples were analysed as received by the laboratory.

Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
30/09/13	1671	Region:Coly, Id:57, Acro:DC400D	<LOR
30/09/13	1672	Region:Coly, Id:3, Acro:DC500A	<LOR
30/09/13	1673	Region:Argoon, Id:5, Acro:CODA	<LOR
30/09/13	1674	Region:Coly, Id:13, Acro:DC500B	<LOR
30/09/13	1675	Region:Argoon, Id:16, Acro:DC820A	<LOR
30/09/13	1676	Region:Argoon, Id:17, Acro:DC800D	<LOR
30/09/13	1677	Region:Yamma, Id:18, Acro:DC800A	<LOR
30/09/13	1678	Region:Yamma, Id:58, Acro:DC800B	<LOR
30/09/13	1679	Region:Yamma, Id:19, Acro:DC800C	<LOR
30/09/13	1680	Region:Yamma, Id:20, Acro:DC830A	<LOR
30/09/13	1681	Region:Yamma, Id:25, Acro:DC840B	<LOR
30/09/13	1682	Region:Yamma, Id:39, Acro:CCD	<LOR
30/09/13	1683	Region:Boona, Id:49, Acro:DC500C	<LOR
30/09/13	1684	Region:Boona, Id:56, Acro:CCS	<LOR
30/09/13	1685	DC820A	<LOR