

Riverina Beef

Regulator Road, Yanco N.S.W. 2703

ANALYSIS REPORT

Report Number: CIC13-09

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 2

The samples were analysed as received by the laboratory.

Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate ($\mu\text{g/L}$)
8/10/13	1790	Region:Coly, Id:57, Acro:DC400D	<LOR
8/10/13	1791	Region:Coly, Id:3, Acro:DC500A	<LOR
8/10/13	1792	Region:Argoon, Id:5, Acro:CODA	<LOR
8/10/13	1793	Region:Coly, Id:13, Acro:DC500B	<LOR
8/10/13	1794	Region:Argoon, Id:16, Acro:DC820A	<LOR
8/10/13	1795	Region:Argoon, Id:17, Acro:DC800D	<LOR
8/10/13	1796	Region:Yamma, Id:18, Acro:DC800A	<LOR
8/10/13	1797	Region:Yamma, Id:58, Acro:DC800B	<LOR
8/10/13	1798	Region:Yamma, Id:19, Acro:DC800C	<LOR
8/10/13	1799	Region:Yamma, Id:20, Acro:DC830A	<LOR
8/10/13	1800	Region:Yamma, Id:25, Acro:DC840B	<LOR
8/10/13	1801	Region:Yamma, Id:39, Acro:CCD	<LOR
8/10/13	1802	Region:Coly, Id:33, Acro:DC550A	<LOR
8/10/13	1803	Region:Boona, Id:50, Acro:DC530A	<LOR
8/10/13	1804	Region:Boona, Id:49, Acro:DC500C	<LOR
8/10/13	1805	Region:Boona, Id:56, Acro:CCS	<LOR