

	JBS Australia RIVERINA BEEF Regulator Road Yanco NSW 2703 Analysis Report	Report No: CIC14-07
---	---	-------------------------------

Report Number: CIC14-07
Customer: Coleambally Irrigation Co-operative
Sample Description: Irrigation Water – Week 1
Date of analysis: 13th October, 2014

The samples were analysed as received by the laboratory.

Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
13/10/14	E0781	Region:Coly, Id:57, Acro:DC400D	<LOR
13/10/14	E0782	Region:Coly, Id:3, Acro:DC500A	<LOR
13/10/14	E0783	Region:Argoon, Id:5, Acro:CODA	<LOR
13/10/14	E0784	Region:Coly, Id:13, Acro:DC500B	<LOR
13/10/14	E0785	Region:Argoon, Id:14, Acro:DC600B	<LOR
13/10/14	E0786	Region:Argoon, Id:16, Acro:DC820A	<LOR
13/10/14	E0787	Region:Argoon, Id:17, Acro:DC800D	<LOR
13/10/14	E0788	Region:Yamma, Id:18, Acro:DC800A	<LOR
13/10/14	E0789	Region:Yamma, Id:58, Acro:DC800B	<LOR
13/10/14	E0790	Region:Yamma, Id:19, Acro:DC800C	<LOR
13/10/14	E0791	Region:Yamma, Id:20, Acro:DC830A	<LOR
13/10/14	E0792	Region:Yamma, Id:25, Acro:DC840B	<LOR
13/10/14	E0793	Region:Coly, Id:33, Acro:DC550A	<LOR
13/10/14	E0794	Region:Boona, Id:50, Acro:DC530A	<LOR
13/10/14	E0795	Region:Boona, Id:49, Acro:DC500C	<LOR
13/10/14	E0796	Region:Boona, Id:46, Acro:DC400B	<LOR
13/10/14	E0797	Region:Boona, Id:56, Acro:CCS	<LOR