

	JBS Australia RIVERINA BEEF Regulator Road Yanco NSW 2703 Analysis Report	Report No: CIC14-21
---	---	-------------------------------

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 8

Date of analysis: 1st December 2014

The samples were analysed as received by the laboratory.

Results for Molinate screen

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
1/12/2014	E1143	Region:Coly, Id:3, Acro:DC500A	<LOR
1/12/2014	E1144	Region:Argoon, Id:5, Acro:CODW	<LOR
1/12/2014	E1145	Region:Argoon, Id:17, Acro:DC800D	<LOR
1/12/2014	E1146	Region:Yamma, Id:18, Acro:DC800A	<LOR
1/12/2014	E1147	Region:Yamma, Id:58, Acro:DC800B	<LOR
1/12/2014	E1148	Region:Yamma, Id:25, Acro:DC840B	<LOR
1/12/2014	E1149	Region:Boona, Id:56, Acro:CCS	<LOR