

Riverina Beef

Regulator Road, Yanco N.S.W. 2703

ANALYSIS REPORT

Report Number: CIC12-027

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 12

The samples were analysed as received by the laboratory.

Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate ($\mu\text{g/L}$)
17/12/2012	2783	Region:Coly, Id:54, Acro:CE160-2	<LOR
17/12/2012	2784	Region:Coly, Id:57, Acro:DC400D	<LOR
17/12/2012	2785	Region:Coly, Id:3, Acro:DC500A	<LOR
17/12/2012	2786	Region:Argoon, Id:5, Acro:CODA	<LOR
17/12/2012	2787	Region:Argoon, Id:14, Acro:DC600B	<LOR
17/12/2012	2788	Region:Argoon, Id:17, Acro:DC800D	<LOR
17/12/2012	2789	Region:Yamma, Id:18, Acro:DC800A	Molinate 1.1 $\mu\text{g/L}$
17/12/2012	2790	Region:Yamma, Id:58, Acro:DC800B	Molinate 0.57 $\mu\text{g/L}$.
17/12/2012	2791	Region:Yamma, Id:19, Acro:DC800C	Molinate 1.1 $\mu\text{g/L}$
17/12/2012	2792	Region:Yamma, Id:20, Acro:DC830A	<LOR
17/12/2012	2793	Region:Yamma, Id:25, Acro:DC840B	<LOR
17/12/2012	2794	Region:Yamma, Id:39, Acro:CCD	<LOR
17/12/2012	2795	Region:Coly, Id:33, Acro:DC550A	<LOR
17/12/2012	2796	Region:Boona, Id:50, Acro:DC530A	<LOR
17/12/2012	2797	Region:Boona, Id:49, Acro:DC500C	<LOR
17/12/2012	2798	Region:Boona, Id:56, Acro:CCS	<LOR