



## ANALYSIS REPORT

**Report Number:** CIC13-15

**Customer:** Coleambally Irrigation Co-operative

**Sample Description:** Irrigation Water – Week 7

The samples were analysed as received by the laboratory.

### Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
11/11/13	2079	Region:Coly, Id:57, Acro:DC400D	<LOR
11/11/13	2080	Region:Coly, Id:3, Acro:DC500A	<LOR
11/11/13	2081	Region:Argoon, Id:5, Acro:CODA	<LOR
11/11/13	2082	Region:Coly, Id:13, Acro:DC500B	<LOR
11/11/13	2083	Region:Argoon, Id:16, Acro:DC820A	Molinate 1.8ug/L
11/11/13	2084	Region:Argoon, Id:17, Acro:DC800D	<LOR
11/11/13	2085	Region:Yamma, Id:18, Acro:DC800A	<LOR
11/11/13	2086	Region:Yamma, Id:58, Acro:DC800B	<LOR
11/11/13	2087	Region:Yamma, Id:19, Acro:DC800C	<LOR
11/11/13	2088	Region:Yamma, Id:20, Acro:DC830A	<LOR
11/11/13	2089	Region:Yamma, Id:25, Acro:DC840B	Molinate 1.4ug/L
11/11/13	2090	Region:Yamma, Id:39, Acro:CCD	<LOR
11/11/13	2091	Region:Coly, Id:33, Acro:DC550A	<LOR
11/11/13	2092	Region:Boona, Id:49, Acro:DC500C	<LOR
11/11/13	2093	Region:Boona, Id:56, Acro:CCS	<LOR