

Riverina Beef

Regulator Road, Yanco N.S.W. 2703

ANALYSIS REPORT

Report Number: CIC13-13

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 5

The samples were analysed as received by the laboratory.

Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
28/10/13	1960	Region:Coly, Id:57, Acro:DC400D	<LOR
28/10/13	1961	Region:Coly, Id:3, Acro:DC500A	<LOR
28/10/13	1962	Region:Argoon, Id:5, Acro:CODA	<LOR
28/10/13	1963	Region:Coly, Id:13, Acro:DC500B	<LOR
28/10/13	1964	Region:Argoon, Id:14, Acro:DC600B	<LOR
28/10/13	1965	Region:Argoon, Id:16, Acro:DC820A	Molinate 0.65ug/L
28/10/13	1966	Region:Argoon, Id:17, Acro:DC800D	<LOR
28/10/13	1967	Region:Yamma, Id:18, Acro:DC800A	Molinate 0.30ug/L
28/10/13	1968	Region:Yamma, Id:58, Acro:DC800B	Molinate 4.4ug/L
28/10/13	1969	Region:Yamma, Id:19, Acro:DC800C	Molinate 2.5ug/L
28/10/13	1970	Region:Yamma, Id:20, Acro:DC830A	<LOR
28/10/13	1971	Region:Yamma, Id:25, Acro:DC840B	<LOR
28/10/13	1972	Region:Yamma, Id:39, Acro:CCD	<LOR
28/10/13	1973	Region:Coly, Id:33, Acro:DC550A	<LOR
28/10/13	1974	Region:Boona, Id:49, Acro:DC500C	<LOR
28/10/13	1975	Region:Boona, Id:56, Acro:CCS	<LOR
28/10/13	1976	Wargum WL	<LOR
28/10/13	1977	Stephens ST	<LOR