

## Riverina Beef

Regulator Road, Yanco N.S.W. 2703

### ANALYSIS REPORT

**Report Number:** CIC12-024

**Customer:** Coleambally Irrigation Co-operative

**Sample Description:** Irrigation Water – Week 10

The samples were analysed as received by the laboratory.

#### Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate ( $\mu\text{g/L}$ )
3/12/12	2654	Region:Coly, Id:54, Acro:CE160-2	<LOR
3/12/12	2655	Region:Coly, Id:57, Acro:DC400D	<LOR
3/12/12	2656	Region:Coly, Id:3, Acro:DC500A	<LOR
3/12/12	2657	Region:Argoon, Id:5, Acro:CODA	<LOR
3/12/12	2658	Region:Coly, Id:13, Acro:DC500B	<LOR
3/12/12	2659	Region:Argoon, Id:14, Acro:DC600B	<LOR
3/12/12	2660	Region:Argoon, Id:17, Acro:DC800D	<LOR
3/12/12	2661	Region:Yamma, Id:18, Acro:DC800A	<LOR
3/12/12	2662	Region:Yamma, Id:58, Acro:DC800B	<LOR
3/12/12	2663	Region:Yamma, Id:19, Acro:DC800C	<LOR
3/12/12	2664	Region:Yamma, Id:20, Acro:DC830A	<LOR
3/12/12	2665	Region:Yamma, Id:25, Acro:DC840B	<LOR
3/12/12	2666	Region:Yamma, Id:39, Acro:CCD	<LOR
3/12/12	2667	Region:Coly, Id:33, Acro:DC550A	<LOR
3/12/12	2668	Region:Boona, Id:49, Acro:DC500C	<LOR
3/12/12	2669	Region:Boona, Id:56, Acro:CCS	<LOR
3/12/12	2670	F33 id: 80	<LOR