

ANALYSIS REPORT

Report Number: CIC12-025

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 11

The samples were analysed as received by the laboratory.

Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate (µg/L)
10/12/12	2713	Region:Coly, Id:54, Acro:CE160-2	<LOR
10/12/12	2714	Region:Coly, Id:57, Acro:DC400D	<LOR
10/12/12	2715	Region:Coly, Id:3, Acro:DC500A	<LOR
10/12/12	2716	Region:Coly, Id:13, Acro:DC500B	<LOR
10/12/12	2717	Region:Argoon, Id:17, Acro:DC800D	<LOR
10/12/12	2718	Region:Yamma, Id:18, Acro:DC800A	<LOR
10/12/12	2719	Region:Yamma, Id:58, Acro:DC800B	Molinate 5.7ug/L all analytes <LOR.
10/12/12	2720	Region:Yamma, Id:19, Acro:DC800C	Molinate 5.1ug/L all other analytes <LOR.
10/12/12	2721	Region:Yamma, Id:20, Acro:DC830A	<LOR
10/12/12	2722	Region:Yamma, Id:25, Acro:DC840B	<LOR
10/12/12	2723	Region:Yamma, Id:39, Acro:CCD	<LOR
10/12/12	2724	Region:Coly, Id:33, Acro:DC550A	<LOR
10/12/12	2725	Region:Boona, Id:50, Acro:DC530A	<LOR
10/12/12	2726	Region:Boona, Id:49, Acro:DC500C	<LOR
10/12/12	2727	F658	<LOR
10/12/12	2728	Id: 79	<LOR
10/12/12	2729	Id: 74	<LOR
10/12/12	2730	Id: 81*	<LOR

Riverina Beef
Regulator Road, Yanco N.S.W. 2703

ANALYSIS REPORT

Date of sample	Sample Number	Sample Description (Type)	Molinate ($\mu\text{g/L}$)
10/12/12	2731	Id: 146	<LOR

Riverina Beef
Regulator Road, Yanco N.S.W. 2703

ANALYSIS REPORT

Report Number: CIC12-026

Customer: Coleambally Irrigation Co-operative

Sample Description: Irrigation Water – Week 11

The sample was analysed as received by the laboratory.

Results for Molinate screen:

Date of sample	Sample Number	Sample Description (Type)	Molinate ($\mu\text{g/L}$)
10/12/12	2768	Region:Argoon, Id:5, Acro:CODA	<LOR